
MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY


Filed: January 11, 2002 Darryl Mexic 202-293-7060

1 of 6



MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY

Filed: January 11, 2002
Darryl Mexic 202-293-7060
2 of 6








FIG.3

MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY

Filed: January 11, 2002 Darryl Mexic 202-293-7060

3 of 6





MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY Filed: January 11, 2002
Darryl Mexic 202-293-7060
4 of 6





FIG.6

 MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY

Filed: January 11, 2002 Darryl Mexic 202-293-7060 5 of 6



MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY Filed: January 11, 2002 Darryl Mexic 202-293-7060 6 of 6

